



PANASONIC

Panasonic 6362 detector service lift

Product code 42125 · Fire alarm systems > Field devices

Rope lift kit for lowering a detector mounted on a high ceiling, together with its mounting base, for testing, maintenance or replacement. Suitable for Panasonic base-mounted smoke and heat detectors.

- The detector and mounting base are lowered on a rope
- Testing, maintenance and detector replacement without a lift platform
- For Panasonic base-mounted smoke and heat detectors
- Suitable for detectors such as 3308, 4400, 4401, 4402 and 4452W



Product description

Panasonic 6362 is an installation kit that turns a detector and its mounting base into a rope lift. With the kit, a detector installed on a high ceiling can be lowered within the user's reach, so that the detector can be tested, maintained or replaced from floor level.

Applications

The service lift is suitable for premises where the ceiling is so high that reaching the detector would otherwise require a lift or scaffolding.

Compatibility

The kit can be used with any Panasonic base-mounted heat or smoke detector. The manufacturer lists the following detectors as related products:

- 3308 analogue heat detector
- 4400 analogue multi-sensor detector
- 4401 analogue optical smoke detector
- 4402 analogue multi-sensor detector with CO detection
- 4452W optical smoke detector

Technical data

Product code	42125
Manufacturer	Panasonic
Product group	Fire alarm systems > Field devices
Weight	70 g
Operating temperature	-10...+50 °C

Humidity	Below 95% RH
Mounting	Ceiling mounting, rope hoist
Compatibility	Panasonic base-mounted smoke and heat detectors, incl. 3308, 4400, 4401, 4402, 4452W

Documents

The manufacturer's original documents can be downloaded from the product page (QR code at the top of this sheet).

Product brochure: Panasonic 6362 detector service lift

Request a quote or ask for more information

Sales +358 40 668 7641 · myynti@pap.fi · Mon–Fri 8 am – 4 pm (Finnish time)

Up-to-date information and documents: pap.fi/en/tuote/panasonic-6362-ilmaisimen-huoltohissi/