



SECURITON

Securiton DFU 535XL RC replacement cartridge for the DFU 535XL filter unit

Product code 61418 · Aspirating smoke detection > Filters and maintenance

Replacement cartridge for the older DFU 535XL dust filter unit.

- > For the DFU 535XL filter unit
- > The successor filter unit is DFU 911

Product description

DFU 535XL RC is Securiton's replacement cartridge for the DFU 535XL dust filter unit. According to Securiton's service information SI98, the DFU 535 filter is replaced every three months. The notice also explains when it is worth replacing the DFU 535 with a DFU 911 unit.

Technical data

Product code	61418
Manufacturer	Securiton
Manufacturer's code	DFU 535XL RC (11-2300070-01-01)
Product group	Aspirating smoke detection > Filters and maintenance
Compatibility	DFU 535XL
Replacement interval	3 months (SI98)

Documents

The manufacturer's original documents can be downloaded from the product page (QR code at the top of this sheet).

Document: Service information SI98 on replacing DFU 535 with DFU 911

Product catalogue (series): SecuriSmoke ASD 2026 (Securiton)

Request a quote or ask for more information

Sales +358 40 668 7641 · myynti@pap.fi · Mon–Fri 8 am – 4 pm (Finnish time)

Up-to-date information and documents: pap.fi/en/tuote/securiton-dfu-535xl-rc/